





**1342 West Adams Blvd.
DEMOLITION: Guttled without permits**



Example of removed window; Pile of window weights removed from multiple windows, and not retained in their original fenestrations.

Entry/Great Room BEFORE (above), and AFTER (below).

This room has been used for 80 years as an auditorium, church sanctuary and gathering place accessible to the public. Note the coved ceiling.





Property Activity Report

[Home](#)

1342 W ADAMS BLVD

[Help](#)

Date Received: 02/15/2013

Description: ANY CHANGES DONE TO A PROPERTY IN AN HISTORICAL AREA

[Parcel Profile Report](#)

Inspector: EDMOND DECKERT

Phone: (323)789-1490

Status: UNDER INVESTIGATION

[LADBS Home](#)

ORDER INFORMATION

Order Number:	Order Type:	Compliance Date:	Issued By:	Phone:
3205268	SUBSTANDARD ORDER	03/27/2013	EDMOND DECKERT	(323)789-1490

[Disclaimer](#)

CODE VIOLATION



Violation:	Date in Compliance:
Historical preservation overlay zone.	N/A
Construction work is being performed without the required permits.	N/A
The building or premises is Substandard due to hazardous electrical wiring.	N/A
The building or premises is Substandard due to defective weather protection for exterior wall coverings.	N/A



Username



Password



[BACK](#) [NEW SEARCH](#)

Leaded glass windows/French doors are a character defining feature.









Sunday church parking



Carriage House is attached to the Church/social hall building -- a zero-foot setback.

