Your Community Impact Statement has been successfully submitted to City Council and Committees.

If you have questions and/or concerns, please contact the Department of Neighborhood Empowerment at <a href="https://NCSupport@lacity.org">NCSupport@lacity.org</a>.

This is an automated response, please do not reply to this email.

**Contact Information** 

Neighborhood Council: Hermon

Name: Jorge Quezada

Phone Number: (818) 425-9976 Email: jorgequezada76@gmail.com

The Board approved this CIS by a vote of: Yea(8) Nay(0) Abstain(0) Ineligible(0) Recusal(0)

Date of NC Board Action: 11-08-2018

Type of NC Board Action: For

Impact Information Date: 11/09/2018

Update to a Previous Input: No


Directed To: City Council and Committees

Council File Number: 14-0163-S17


Agenda Date: 11/08/2018

Item Number: 13

Summary: The Hermon Community is a peaceful and tranquil place to live. However, there are issues that any neighborhood will have to contend with. In 2016 it was the homeless population that overpopulated the Arroyo. In 2017 petty crimes involving car break ins were rampant. Those issues, for the most part, have dissipated. In 2018, our top priority is sidewalk repair. In August 2018, the Hermon Neighborhood Council hosted an event with Councilmember Huizar with approximately 75 residents. The residents overwhelmingly voiced their concern with buckling and broken sidewalks that are a tremendous public safety hazard. Our community is made up of lots of families and elderly. Becuase of the failing sidewalks, families with kids that push their kids in baby carriages have a hard time maneuvering through broken sidewalks. The elderly find it difficult to meander their wheelchairs around broken sidewalks an at times have no choice but to meander into streets. The Hermon Neighborhood Council has put together an in-depth analysis focusing on sidewalk conditions in Hermon. This is our top priority and we ask the City Council and the Department of Public Works to address this issue to avoid a tragedy. The sidewalks analysis is attached and can be viewed at: http://hermonnc.org/wp-content/uploads/2018/10/HermonStreetMapImages\_LO.pdf Thank you, Hermon Neighborhood Council HermonNC.org




#### SAMPLES OF DAMAGE DESCRIPTIONS






LOCATION: 433 & 437 Wheeling Way

DESCRIPTION: Driveway bibs Cracked & Spidering



LOCATION: Via Marisol area West of Avenue 60

DESCRIPTION:
Problems in area is known
Complete street and sidewalk repair has been budgeted by the city of Los Angeles for 2019







LOCATION: Wheeling Way


DESCRIPTION: Sidewalk crossing above stepstreet broken and sinking.






LOCATION: Wheeling Way step street down to Via Marisol

DESCRIPTION: Steps and edging broken, shifting and in disrepair






LOCATION: Bushnell Way at Wheeling Way

DESCRIPTION: Sidewalk missing and severly dropped area from ground movement.







LOCATION: Kendall at Monterey Between 432 Kendall and Monterey Road

DESCRIPTION:
A few lifted areas
around trees. Prevoiusly patched with
asphalt










Monterey Road Ebey Ave Lomitas Dr S. Ave 59 Hellman Ave Wheeling Way Coleman Ave Redfield Ave Rendall Ave Terrill Ave Pullman Hawley Ave

LOCATION: Across the street from 5916 Ebey Way (Behind Fresco Market)

DESCRIPTION: Cracked and lifted section around water connection and tree.





LOCATION: 5444 Monterey Road (Just South of Kendall)


DESCRIPTION: Drop in sidewalk around water meter. cracking at corners





LOCATION: 5500-5506 Monterey Road (Just North of Kendall)

DESCRIPTION: Lift in sidewalk. previous repair is broken and worn.





LOCATION: 502-510 Colman Ave (at Monterey Road)

DESCRIPTION: Lift in sidewalk. previous repair is broken and worn.



LOCATION: 520 Redfield Ave

DESCRIPTION: Spidering and cracking driveway bib and sidewalk edging.




LOCATION: Redfield Ave exact address unkown

DESCRIPTION: Large lifted sections. Previous repair is worn and chipped



LOCATION: 511 Coleman Ave

DESCRIPTION: Spidering and cracking sidewalk and driveway bib.



LOCATION: 520 Terrill Ave

DESCRIPTION:
Borken curb dropping and lifting of sidewalk and driveway bib.



# LOCATION: Pullman Way

DESCRIPTION:
No sidewalks or
curbs. Images show
street and gutter
conditions.
Street is asphalt with
no curb.
Unfinished repair and
equipment.








LOCATION: Hawley Ave

DESCRIPTION:
No sidewalks or
curbs. Image shows
crumbling street and
gutter condition.
Street is asphalt with
no curb.



LOCATION: Redfield Ave exact address unkown

DESCRIPTION: Large lifted section with loose piece.



LOCATION: 508 Redfield Ave

DESCRIPTION: Worn Patch Areas



LOCATION: 518 Redfield Ave

DESCRIPTION: Worn Patch Areas





LOCATION: 520 Redfield Ave exact address unkown

DESCRIPTION: Large lifted section with loose piece.



LOCATION: 524 Redfield Ave

DESCRIPTION: Lifted section




LOCATION: 528 Redfield Ave

DESCRIPTION: lifted section




LOCATION: 544-548 Redfield Ave

DESCRIPTION: Large lifted section Worn Patch Areas



LOCATION: 552 Redfield Ave


DESCRIPTION:
Large lifted section
with loose piece. Spidering and cracking.
Drop and lifting in
sections.



LOCATION: 560 Redfield Ave

DESCRIPTION: Worn Patch Areas





Monterey Road Lomitas Dr Short Way Pine Crest Drive Toltec Way Hardison Way Avenue 60

Dak Hill Development Milford St S. Ave 61 Shafter Way Lomitas Drive


LOCATION: Between 457 S. Ave 60 and 110 frwy on ramp

DESCRIPTION: Cracking & Spidering depression on vegitation side. Previously repaired with asphalt fill.



LOCATION: Ave 60 at Monterey sidewalk and driveway in front of Union 76 gas station

DESCRIPTION: Cracking & gaps



LOCATION: 617 S Ave 60

DESCRIPTION: Cracked and lifted section of sidewalk and curb. Previously patched with asphalt.



LOCATION: 6215 Monterey Road

DESCRIPTION: Lift in sidewalk with asphalt patch repair





LOCATION: 6209 Monterey Road

DESCRIPTION: Lift in sidewalk with asphalt patch repair. long crack at base of lifted area.



HERMON NORTH LOCATION: Hardison Way

DESCRIPTION:
No sidewalks.
Images show street and curb condition.
Street is concrete with curb.



HERMON NORTH LOCATION: Toltec Way

DESCRIPTION: No sidewalks.

HERMON NORTH LOCATION: 703 S. Ave 60

DESCRIPTION: Sidewalk has lifted section that couls be flattened/repaired.

# HERMON NORTH LOCATION: 6336 Monterey Road

DESCRIPTION:
Street edge along
gutter collects water
and does not properly drain. Water will sit
for days until it evaporates. Water source
is unknown.

