

JUN 25 2013

PUBLIC WORKS

13-0808
CD12

MOTION

Council District 12 has identified an off-grade curb and gutter problem at the intersection of Reseda Boulevard and Lemarsh Street resulting in the significant pooling of water. The problem is exacerbated by the collection of large amounts of trash which blocks the storm drains resulting in the pooling of water.


Water flowing down Lemarsh Street from residential lawn watering and water discharge from the Bureau of Street Services Granada Hills Maintenance Yard (Maintenance Yard) have been contributing factors to the water pooling at Reseda Boulevard intersection. Residents have observed water discharging from the Maintenance Yard onto Lemarsh Street at night and in the early morning hours.

In its efforts to resolve this problem, the Council District is seeking the assistance of the Bureau of Street Services to review the discharge from its Granada Hills Maintenance Yard onto Lemarsh Street and to recommend a course of action to remediate the water pooling problem at the Reseda Boulevard and Lemarsh Street intersection.

I THEREFORE MOVE that the Department of Public Works, Bureau of Street Services, be instructed to prepare and present a report, including recommendations, relative to the discharge of water onto Lemarsh Street from its Granada Hills Maintenance Yard (10210 Etiwanda Avenue); such report to include an analysis of the discharged fluid, when the discharge occurs, amounts that are being discharged, the cause of the discharge and any actions necessary to remediate the pooling of water at the Reseda Boulevard and Lemarsh Street intersection.

I FURTHER MOVE that the Bureau of Street Services present their report to the Planning and Land Use Management Committee.

PRESENTED BY: 
MITCHELL ENGLANDER
Councilmember, 12th District

SECONDED BY: 

ps 
JUN 25 2013

ORIGINAL